

My Car.car - CarChip

File Setup CarChip View Help Diagnostics

Trip 3 Report Plot Table Comments

View / Trip Log / Trip 3 / Report

Vehicle Ford Aspire
 CarChip Z-0084-Z

Start Time 10/22/2002 3:58 PM
 End Time 10/22/2002 4:42 PM
 Duration 0:44:35
 Idle 0:02:09
 0 to 45 MPH 0:19:01
 45 to 60 MPH 0:06:46
 60 to 75 MPH 0:16:22
 Over 75 MPH 0:00:14

Distance 30.9 Miles
 Average Speed 42 MPH
 Maximum Speed 79 MPH

Hard Brakes 4 (Between 0.28 G and 0.48 G)
 Extreme Brakes 0 (Over 0.48 G)


Hard Accelerations 4 (Between 0.28 G and 0.48 G)
 Extreme Accelerations 0 (Over 0.48 G)

Parameters
 Parameter 1 Vehicle Speed Every 5 Seconds
 Parameter 2 Engine Speed Every 5 Seconds
 Parameter 3 Coolant Temperature Every 5 Seconds
 Parameter 4 Intake Air Temperature Every 5 Seconds
 Parameter 5 Battery Voltage Every 5 Seconds

Comments

Trip Logging

For help, press F1. CarChip Detected on COM1 : Z-0084-Z



View / Activity Log / Summary

Event	Time	TripLogger	Description
Event 1	12/31/1989 4:01 PM	Z-0084-Z	Speed bands altered.
Event 2	12/31/1989 4:00 PM	Z-0084-Z	Logs downloaded.
Event 3	10/21/2002 8:19 AM	Z-0084-Z	Logs downloaded.
Event 4	10/21/2002 4:55 PM	Z-0084-Z	Parameters altered.
Event 5	10/21/2002 4:55 PM	Z-0084-Z	
Event 6	10/21/2002 5:01 PM	Z-0084-Z	
Event 7	10/22/2002 6:29 AM	Z-0084-Z	Connected to Ford Aspire.
Event 8	10/22/2002 7:11 AM	Z-0084-Z	Disconnected.
Event 9	10/22/2002 7:18 AM	Z-0084-Z	Logs downloaded.
Event 10	10/22/2002 1:47 PM	Z-0084-Z	Logs downloaded.
Event 11	10/22/2002 1:47 PM	Z-0084-Z	Logs downloaded.
Event 12	10/22/2002 3:58 PM	Z-0084-Z	Connected to Ford Aspire.
Event 13	10/23/2002 7:38 AM	Z-0084-Z	Disconnected.
Event 14	10/23/2002 7:40 AM	Z-0084-Z	Logs downloaded.
Event 15	10/23/2002 7:41 AM	Z-0084-Z	Logs downloaded.
Event 16	10/23/2002 9:43 AM	Z-0084-Z	Logs downloaded.
Event 17	10/23/2002 9:48 AM	Z-0084-Z	Logs downloaded.
Event 18	10/23/2002 9:52 AM	Z-0084-Z	Logs downloaded.
Event 19	10/23/2002 9:53 AM	Z-0084-Z	Logs downloaded.
Event 20	10/23/2002 12:04 PM	Z-0084-Z	Logs downloaded.
Event 21	10/23/2002 12:21 PM	Z-0084-Z	Logs downloaded.
Event 22	10/23/2002 12:40 PM	Z-0084-Z	Date or time altered.
Event 23	10/23/2002 1:29 PM	Z-0084-Z	Logs downloaded.

Activity Log

For help, press F1.

CarChip Detected on COM1 : Z-0084-Z

My Car.car - CarChip

File Setup CarChip View Help

Problem 1 Comments

View / Vehicle Trouble Log / Problem 1

Overview

Time: 10/18/2002 6:50 AM
 Vehicle: Ford F-150
 CarChip: Dan P.
 Trouble Code: P0010
 Description: "A" Camshaft Position - Actuator Circuit (Bank 1)
 Comments:

Engine Status

Fuel Pressure (Gage): 1.1 psi
 Intake Manifold Pressure (Absolute): 9.8 psi
 Engine Coolant Temperature: 103.0 °F
 Calculated Load Value: 40.0 %
 Engine Speed: 2,100 RPM
 Vehicle Speed: 18 MPH

Fuel Trim Status

Short-Term Fuel Trim (Bank 1): 52.00 %
 Short-Term Fuel Trim (Bank 2):
 Long-Term Fuel Trim (Bank 1): 49.30 %
 Long-Term Fuel Trim (Bank 2):


Fuel System Status

Fuel System 1 Status: Open loop; has not yet satisfied conditions to go to closed loop.
 Fuel System 2 Status:

Comments.....

Trouble Logging

For help, press F1. CarChip Detected on COM1 : Z-0084Z



My Car.car - CarChip
File Setup CarChip View Help

E/X & Fleet Models Only

CarChip / Choose Other Parameters

Parameter	Name	Interval
Parameter 1	Vehicle Speed	5 Seconds
Parameter 2	Engine Speed	5 Seconds
Parameter 3	Coolant Temperature	5 Seconds
Parameter 4	Intake Air Temperature	5 Seconds
Parameter 5	Battery Voltage	5 Seconds

Buttons: OK, Cancel, Help, Default

Monitor Multiple Parameters

For help, press F1. CarChip Detected on COM1 : Z-0084-Z

My Car.car - CarChip
File Setup CarChip View Help

Trip 1 | Report | Plot | Table | Comments

View / Trip Log / Trip 1 / Plot / Coolant Temperature (°F)

E/X & Fleet Models Only

Coolant Temp. Graphing

06:45:22 AM; 82.5 °F CarChip Detected on COM1 : Z-0084-Z